APPENDIX D

Boater Survey Results

APPENDIX D-1

Boater Survey Results for Individual Survey Questions

Table D-1. Owner of the Boat (Q1)

| Owner | Number | Weighted Percent | Standard Error |
|---------|--------|---------------------|-------------------|
| Yes | 907 | 95.2 | 1.1 |
| No | 46 | 4.8 | 1.1 |
| Missing | 5 | - | |

Figure D-1. Owner of the Boat (Q1)




Table D-2. Length of Boat (Q2)

| Length (feet) | Number | Weighted Percent | Standard Error |
|---------------|--------|---------------------|-------------------|
| <20 | 57 | 6.3 | 1.5 |
| 20-24.9 | 113 | 12.5 | 1.3 |
| 25-29.9 | 219 | 22.8 | 1.9 |
| 30-34.9 | 219 | 23.4 | 1.5 |
| 35-39.9 | 142 | 14.6 | 1.3 |
| 40-44.9 | 107 | 10.7 | 1.2 |
| 45+ | 99 | 9.9 | 1.3 |
| Missing | 2 | | |

Figure D-2. Length of Boat (Q2)




Table D-3. Draft of Boat (Q3)

| Draft (feet) | Number | Weighted Percent | Standard Error |
|--------------|--------|---------------------|-------------------|
| <2.0 | 89 | 10.1 | 1.8 |
| 2-2.9 | 182 | 20.5 | 1.7 |
| 3-3.9 | 337 | 36.2 | 2.1 |
| 4-4.9 | 163 | 17.6 | 1.4 |
| 5+ | 151 | 15.7 | 2.1 |
| Missing | 36 | | |

Figure D-3. Draft of Boat (Q3)




Table D-4. Function of Boat (Q4)

| Function | Response | Number | Weighted Percent | Standard Error |
|--------------|----------|--------|---------------------|-------------------|
| Commercial | Yes | 51 | 7.9 | 1.4 |
| Commercial | No | 632 | 92.1 | 1.4 |
| Commercial | Missing | 275 | | |
| Recreational | Yes | 866 | 93.9 | 1.4 |
| Recreational | No | 54 | 6.1 | 1.4 |
| Recreational | Missing | 38 | | |
| Live Aboard | Yes | 124 | 17.3 | 2.6 |
| Live Aboard | No | 590 | 82.7 | 2.6 |
| Live Aboard | Missing | 244 | | |

Figure D-4. Function of Boat (Q4)




Table D-5. Type of Boat (Q5)

| ĺ | Type | Response | Number | Weighted Percent | Standard Error |
|---|-------|----------|--------|---------------------|-------------------|
| ı | Power | Yes | 764 | 85.5 | 2.8 |
| | Power | No | 129 | 14.5 | 2.8 |
| | Power | Missing | 65 | | |
| | Sail | Yes | 198 | 26.8 | 3.6 |
| | Sail | No | 524 | 73.2 | 3.6 |
| I | Sail | Missing | 236 | | |

Figure D-5. Type of Boat (Q5)




Table D-6. Type of Toilet in Boat (Q6)

| Toilet Type | Response | Number | Weighted Percent | Standard Error |
|-------------|----------|--------|---------------------|-------------------|
| Portable | Yes | 136 | 14.8 | 1.7 |
| Portable | No | 820 | 85.2 | 1.7 |
| Portable | Missing | 2 | | |
| Installed | Yes | 746 | 77.5 | 2.1 |
| Installed | No | 210 | 22.5 | 2.1 |
| Installed | Missing | 2 | | |

Figure D-6. Type of Toilet in Boat (Q6)




Table D-7. Type of Installed Toilet in Boat (Q7)

| Toilet Type | Response | Number | Weighted Percent | Standard Error |
|----------------|------------------|--------|---------------------|-------------------|
| Flow Through | Yes | 134 | 19.2 | 2.4 |
| Flow Through | No | 613 | 80.8 | 2.4 |
| Flow Through | Missing | 1 | | - |
| Flow Through | Appropriate skip | 210 | | |
| Holding Tank | Yes | 736 | 98.5 | 0.4 |
| Holding Tank | No | 11 | 1.5 | 0.4 |
| Holding Tank | Missing | 1 | | |
| Holding Tank | Appropriate skip | 210 | | |

Figure D-7. Type of Installed Toilet in Boat (Q7)




Table D-8. Service and Performance of Installed Toilet (Q8)

| Performance | Response | Number | Weighted Percent | Standard Error |
|-------------|------------------|--------|---------------------|-------------------|
| Reg Service | Yes | 656 | 90.1 | 1.7 |
| Reg Service | No | 74 | 9.9 | 1.7 |
| Reg Service | Missing | 18 | | |
| Reg Service | Appropriate skip | 210 | | |
| Add Chem | Yes | 526 | 73.0 | 4.1 |
| Add Chem | No | 188 | 27.0 | 4.1 |
| Add Chem | Missing | 34 | | |
| Add Chem | Appropriate skip | 210 | | |
| Reg Chem | Yes | 530 | 73.7 | 2.6 |
| Reg Chem | No | 194 | 26.3 | 2.6 |
| Reg Chem | Missing | 24 | | |
| Reg Chem | Appropriate skip | 210 | | |
| Adequate | Yes | 710 | 97.2 | 0.7 |
| Adequate | No | 20 | 2.8 | 0.7 |
| Adequate | Missing | 18 | | . |
| Adequate | Appropriate skip | 210 | | |

Figure D-8. Service and Performance of Installed Toilet (Q8)




Table D-9. Source of Training for Operation of Installed Toilet (Q9)

| Source | Response | Number | Weighted Percent | Standard Error |
|--------------|------------------|--------|---------------------|-------------------|
| Dealer | Yes | 176 | 24.4 | 2.7 |
| Dealer | No | 572 | 75.6 | 2.7 |
| Dealer | Appropriate skip | 210 | | |
| Manufacturer | Yes | 31 | 3.8 | 0.7 |
| Manufacturer | No | 717 | 96.2 | 0.7 |
| Manufacturer | Appropriate skip | 210 | | |
| Marina | Yes | 24 | 3.4 | 0.7 |
| Marina | No | 724 | 96.6 | 0.7 |
| Marina | Appropriate skip | 210 | | |
| Manual | Yes | 299 | 39.4 | 2.6 |
| Manual | No | 449 | 60.6 | 2.6 |
| Manual | Appropriate skip | 210 | | |
| None | Yes | 261 | 34.8 | 2.3 |
| None | No | 487 | 65.2 | 2.3 |
| None | Appropriate skip | 210 | | |
| Other | Yes | 33 | 4.6 | 0.8 |
| Other | No | 717 | 95.4 | 0.8 |
| Other | Appropriate skip | 208 | | |

Figure D-9. Source of Training for Operation of Installed Toilet (Q9)




Table D-10. Length of Training for Proper Use (Q10)

| Training Length | Number | Weighted Percent | Standard Error |
|--------------------|--------|---------------------|-------------------|
| <30 min | 155 | 76.5 | 4.1 |
| 30 min - 1 hour | 30 | 13.9 | 2.3 |
| 2 hours | 7 | 4.6 | 2.7 |
| Half day | 7 | 3.0 | 1.0 |
| Full day | 5 | 2.0 | 1.0 |
| Missing | 7 | - | |
| Appropriate skip | 747 | | |

Figure D-10. Length of Training for Proper Use (Q10)




Table D-11. Operation of Installed Toilet in NDZ (Q11)

| Operation | Response | Number | Weighted Percent | Standard Error |
|-----------|------------------|--------|---------------------|-------------------|
| Y-valve | Yes | 162 | 24.1 | 3.7 |
| Y-valve | No | 586 | 75.9 | 3.7 |
| Y-valve | Appropriate skip | 210 | . 0.0 | · · · |
| Holding | Yes | 618 | 82.5 | 2.5 |
| Holding | No | 130 | 17.5 | 2.5 |
| Holding | Appropriate skip | 210 | | |
| Don't Use | Yes | 94 | 12.4 | 2.0 |
| Don't Use | No | 654 | 87.6 | 2.0 |
| Don't Use | Appropriate skip | 210 | | |
| Normal | Yes | 45 | 6.3 | 1.6 |
| Normal | No | 703 | 93.7 | 1.6 |
| Normal | Appropriate skip | 210 | | |
| Other | Yes | 4 | 0.7 | 0.4 |
| Other | No | 744 | 99.3 | 0.4 |
| Other | Appropriate skip | 210 | | |

Figure D-11. Operation of Installed Toilet in NDZ (Q11)




Table D-12. Number of Days Boated in the 2003 Season (Q12)

| Days | Number | Weighted Percent | Standard Error |
|------------------|--------|---------------------|-------------------|
| 0 | 21 | 2.6 | 0.6 |
| 1-9 | 115 | 13.4 | 1.3 |
| 10-19 | 125 | 13.9 | 1.7 |
| 20-29 | 165 | 18.9 | 1.4 |
| 30-39 | 141 | 17.0 | 1.4 |
| 40-49 | 57 | 6.8 | 1.0 |
| 50-99 | 123 | 14.4 | 1.6 |
| 100+ | 118 | 13.1 | 1.5 |
| Missing | 9 | | - |
| Appropriate skip | 84 | | |

Figure D-12. Number of Days Boated in the 2003 Season (Q12)




Table D-13. Number of Days Boated in the NDZ in the 2003 Season (Q13)

| Days | Number | Weighted Percent | Standard Error |
|------------------|--------|---------------------|-------------------|
| 0 | 60 | 7.8 | 2.6 |
| 1-9 | 178 | 21.5 | 2.0 |
| 10-19 | 143 | 16.5 | 1.0 |
| 20-29 | 158 | 17.4 | 1.5 |
| 30-39 | 97 | 11.9 | 1.1 |
| 40-49 | 50 | 5.8 | 0.9 |
| 50-99 | 91 | 10.2 | 1.6 |
| 100+ | 75 | 9.0 | 1.3 |
| Missing | 22 | | |
| Appropriate skip | 84 | | |

Figure D-13. Number of Days Boated in the NDZ in the 2003 Season (Q13)




Table D-14. Type of Sewage Discharge Facility Used in 2003 (Q14)

| Facility | Response | Number | Weighted Percent | Standard Error |
|--------------|------------------|--------|---------------------|-------------------|
| Station Pump | Yes | 430 | 51.7 | 3.2 |
| Station Pump | No | 383 | 48.3 | 3.2 |
| Station Pump | Missing | 61 | | |
| Station Pump | Appropriate skip | 84 | | |
| Mobile Pump | Yes | 244 | 31.3 | 3.3 |
| Mobile Pump | No | 521 | 68.7 | 3.3 |
| Mobile Pump | Missing | 109 | | |
| Mobile Pump | Appropriate skip | 84 | | |
| Shore Pump | Yes | 159 | 20.6 | 2.9 |
| Shore Pump | No | 608 | 79.4 | 2.9 |
| Shore Pump | Missing | 107 | | |
| Shore Pump | Appropriate skip | 84 | | |
| Toilet Dump | Yes | 47 | 7.0 | 1.1 |
| Toilet Dump | No | 686 | 93.0 | 1.1 |
| Toilet Dump | Missing | 141 | | |
| Toilet Dump | Appropriate skip | 84 | | |

Figure D-14. Type of Sewage Discharge Facility Used in 2003 (Q14)




Table D-15. Arrangement with Marina to Pump Out Tank During Boater Absence (Q15)

| Arrangement | Number | Weighted Percent | Standard Error |
|------------------|--------|---------------------|-------------------|
| Yes | 74 | 9.8 | 2.6 |
| No | 748 | 90.2 | 2.6 |
| Missing | 52 | - | |
| Appropriate skip | 84 | | |

Figure D-15. Arrangement with Marina to Pump Out Tank During Boater Absence (Q15)




Table D-16. Pumpout or Toilet Dump Facility Used in 2003 (Q16)

| Facility Used | Number | Weighted Percent | Standard Error |
|------------------|--------|---------------------|-------------------|
| Yes | 524 | 60.3 | 2.7 |
| No | 336 | 39.7 | 2.7 |
| Missing | 14 | - | - |
| Appropriate skip | 84 | | |

Figure D-16. Pumpout or Toilet Dump Facility Used in 2003 (Q16)




Table D-17. Number of Times Pumpout or Toilet Dump Facility was Used in 2003 (Q16A)

| Number of Times | Number | Weighted Percent | Standard Error |
|------------------|--------|---------------------|-------------------|
| 1 | 70 | 14.4 | 1.9 |
| 2 | 82 | 16.6 | 1.4 |
| 3-4 | 104 | 20.9 | 1.9 |
| 5-9 | 106 | 20.1 | 1.9 |
| 10-19 | 95 | 18.1 | 1.8 |
| 20+ | 52 | 9.8 | 1.4 |
| Missing | 25 | | |
| Appropriate skip | 84 | | |
| Not applicable | 340 | | |

Figure D-17. Number of Times Pumpout or Toilet Dump Facility was Used in 2003 (Q16A)




Table D-18. Trouble with a Pumpout or Toilet Dump Facility in 2003 (Q17)

| Trouble | Number | Weighted Percent | Standard Error |
|------------------|--------|---------------------|-------------------|
| Yes | 79 | 9.2 | 1.4 |
| No | 632 | 74.2 | 2.4 |
| No attempt | 141 | 16.6 | 1.7 |
| Missing | 21 | | |
| Appropriate skip | 85 | | |

Figure D-18. Trouble with a Pumpout or Toilet Dump Facility in 2003 (Q17)




Table D-19. Number of Times a Boater had Trouble with a Pumpout or Toilet Dump Facility (Q17A)

| Number of Times | Number | Weighted Percent | Standard Error |
|------------------|--------|---------------------|-------------------|
| 1 | 21 | 30.0 | 5.2 |
| 2 | 23 | 27.5 | 6.5 |
| 3-4 | 10 | 14.4 | 2.7 |
| 5-9 | 17 | 22.3 | 3.2 |
| 10-19 | 3 | 4.5 | 3.3 |
| 20+ | 1 | 1.3 | 1.2 |
| Missing | 23 | | |
| Appropriate skip | 85 | | |
| Not applicable | 775 | | |

Figure D-19. Number of Times a Boater had Trouble with a Pumpout or Toilet Dump Facility (Q17A)




Table D-20. Trouble with the Pumpout or Toilet Dump Facilities on Last Trip in NDZ (Q18)

| Trouble | Number | Weighted Percent | Standard Error |
|------------------|--------|---------------------|-------------------|
| Yes | 24 | 2.5 | 0.7 |
| No | 589 | 70.4 | 2.5 |
| No attempt | 229 | 27.1 | 2.4 |
| Missing | 27 | | |
| Appropriate skip | 89 | | |

Figure D-20. Trouble with the Pumpout or Toilet Dump Facilities on Last Trip in NDZ (Q18)




Table D-21. Could Not Find Working Pumpout or Toilet Dump This Season in NDZ (Q19)

| Could Not Find | Number | Weighted Percent | Standard Error |
|------------------|--------|---------------------|-------------------|
| Yes | 57 | 7.2 | 1.0 |
| No | 794 | 92.8 | 1.0 |
| Missing | 23 | - | - |
| Appropriate skip | 84 | | |

Figure D-21. Could Not Find Working Pumpout or Toilet Dump This Season in NDZ (Q19)




Table D-22. Discharged Sewage Outside the NDZ (Q20)

| Discharged | Number | Weighted Percent | Standard Error |
|------------------|--------|---------------------|-------------------|
| Yes | 202 | 24.6 | 3.0 |
| No | 651 | 75.4 | 3.0 |
| Missing | 21 | | |
| Appropriate skip | 84 | | |

Figure D-22. Discharged Sewage Outside the NDZ (Q20)




Table D-23. Number of Times Boater Discharged Sewage Outside the NDZ (Q20A)

| Number of Times | Number | Weighted Percent | Standard Error |
|------------------|--------|---------------------|-------------------|
| 1 | 36 | 18.7 | 2.1 |
| 2 | 42 | 23.0 | 2.4 |
| 3-4 | 38 | 19.5 | 1.8 |
| 5-9 | 29 | 13.8 | 1.8 |
| 10-19 | 27 | 14.2 | 2.0 |
| 20+ | 25 | 10.8 | 1.9 |
| Missing | 25 | | |
| Appropriate skip | 84 | | |
| Not applicable | 652 | | |

Figure D-23. Number of Times Boater Discharged Sewage Outside the NDZ (Q20A)




Table D-24. Conditions Found at Pumpout or Toilet Dump Facilities in the NDZ in 2003 (Q21)

| Condition | Response | Number | Weighted Percent | Standard Error |
|-----------------|------------------|--------|---------------------|-------------------|
| Closed | Yes | 38 | 5.3 | 0.9 |
| Closed | No | 660 | 94.7 | 0.9 |
| Closed | Missing | 176 | | |
| Closed | Appropriate skip | 84 | | |
| No Pumpout | Yes | 52 | 7.0 | 1.4 |
| No Pumpout | No | 651 | 93.0 | 1.4 |
| No Pumpout | Missing | 171 | | |
| No Pumpout | Appropriate skip | 84 | | |
| Not Functioning | Yes | 101 | 14.1 | 2.1 |
| Not Functioning | No | 603 | 85.9 | 2.1 |
| Not Functioning | Missing | 170 | | |
| Not Functioning | Appropriate skip | 84 | | |
| No Staff | Yes | 40 | 5.9 | 1.3 |
| No Staff | No | 657 | 94.1 | 1.3 |
| No Staff | Missing | 177 | | |
| No Staff | Appropriate skip | 84 | | |
| Knowledge | Yes | 10 | 1.3 | 0.3 |
| Knowledge | No | 682 | 98.7 | 0.3 |
| Knowledge | Missing | 182 | | |
| Knowledge | Appropriate skip | 84 | | |
| Inaccessible | Yes | 31 | 4.3 | 0.9 |
| Inaccessible | No | 665 | 95.7 | 0.9 |
| Inaccessible | Missing | 178 | | |
| Inaccessible | Appropriate skip | 84 | | |
| Mobile Unavail | Yes | 29 | 4.2 | 0.8 |
| Mobile Unavail | No | 662 | 95.8 | 0.8 |
| Mobile Unavail | Missing | 183 | | |
| Mobile Unavail | Appropriate skip | 84 | | |
| Waiting Time | Yes | 33 | 5.0 | 1.4 |
| Waiting Time | No | 660 | 95.0 | 1.4 |
| Waiting Time | Missing | 181 | | |
| Waiting Time | Appropriate skip | 84 | | |

| High Cost | Yes | 31 | 4.6 | 1.0 |
|-------------|------------------|-----|------|-----|
| High Cost | No | 666 | 95.4 | 1.0 |
| High Cost | Missing | 177 | | |
| High Cost | Appropriate skip | 84 | | |
| Distance | Yes | 13 | 2.0 | 0.5 |
| Distance | No | 674 | 98.0 | 0.5 |
| Distance | Missing | 187 | • | |
| Distance | Appropriate skip | 84 | - | |
| No Problems | Yes | 431 | 55.3 | 5.8 |
| No Problems | No | 303 | 44.7 | 5.8 |
| No Problems | Missing | 140 | - | |
| No Problems | Appropriate skip | 84 | - | |

Figure D-24. Conditions Found at Pumpout or Toilet Dump Facilities in the NDZ in 2003 (Q21)




Table D-25. Conditions or Problems in Q21 Deterred Boater from Using Facilities (Q22)

| | Deterred Boater | Number | Weighted Percent | Standard Error |
|---|------------------|--------|---------------------|-------------------|
| ı | Yes | 78 | 10.4 | 1.1 |
| ı | No | 667 | 89.6 | 1.1 |
| ı | Missing | 97 | | |
| ı | Appropriate skip | 116 | | |

Figure D-25. Conditions or Problems in Q21 Deterred Boater from Using Facilities (Q22)




Table D-26. Number of Times Conditions or Problems Deterred Boater from Using Facilities (Q22A)

| Number of Times | Number | Weighted Percent | Standard Error |
|------------------|--------|---------------------|-------------------|
| 1 | 22 | 33.7 | 5.6 |
| 2 | 15 | 20.6 | 3.7 |
| 3-4 | 15 | 22.4 | 4.0 |
| 5-9 | 6 | 11.6 | 5.4 |
| 10-19 | 7 | 10.7 | 4.7 |
| 20+ | 1 | 1.1 | 0.9 |
| Missing | 109 | | |
| Appropriate skip | 116 | | |
| Not applicable | 667 | | |

Figure D-26. Number of Times Conditions or Problems Deterred Boater from Using Facilities (Q22A)




Table D-27. Knowledge Whether or Not Designated Area is an NDZ (Q23)

| Knowledge | Number | Weighted Percent | Standard Error |
|-----------|--------|---------------------|-------------------|
| Yes | 892 | 94.2 | 0.9 |
| No | 54 | 5.8 | 0.9 |
| Missing | 12 | | |

Figure D-27. Knowledge Whether or Not Designated Area is an NDZ (Q23)




Table D-28. Knowledge that Discharge of Vessel Sewage is Prohibited in the NDZ (Q24)

| Knowledge | Number | Weighted Percent | Standard Error |
|-----------|--------|---------------------|-------------------|
| Yes | 914 | 97.1 | 0.7 |
| No | 28 | 2.9 | 0.7 |
| Missing | 16 | | |

Figure D-28. Knowledge that Discharge of Vessel Sewage is Prohibited in the NDZ (Q24)




Table D-29. Source of Information about NDZ (Q25)

| Source | Response | Number | Weighted Percent | Standard Error |
|---------------------|----------|--------|---------------------|-------------------|
| TV | Yes | 105 | 16.9 | 3.0 |
| TV | No | 591 | 83.1 | 3.0 |
| TV | Missing | 262 | | |
| Radio | Yes | 80 | 13.0 | 2.3 |
| Radio | No | 611 | 87.0 | 2.3 |
| Radio | Missing | 267 | | |
| Boat Show | Yes | 233 | 33.2 | 3.5 |
| Boat Show | No | 475 | 66.8 | 3.5 |
| Boat Show | Missing | 250 | | |
| Marina Signs | Yes | 364 | 51.1 | 6.2 |
| Marina Signs | No | 382 | 48.9 | 6.2 |
| Marina Signs | Missing | 212 | | |
| Marina Brochures | Yes | 237 | 35.1 | 6.3 |
| Marina Brochures | No | 499 | 64.9 | 6.3 |
| Marina Brochures | Missing | 222 | | |
| Marina Verbal | Yes | 243 | 34.6 | 5.7 |
| Marina Verbal | No | 487 | 65.4 | 5.7 |
| Marina Verbal | Missing | 228 | - | |
| Signs Elsewhere | Yes | 292 | 41.8 | 5.1 |
| Signs Elsewhere | No | 442 | 58.2 | 5.1 |
| Signs Elsewhere | Missing | 224 | | |
| Brochures Elsewhere | Yes | 273 | 39.7 | 4.0 |
| Brochures Elsewhere | No | 443 | 60.3 | 4.0 |
| Brochures Elsewhere | Missing | 242 | | |
| Verbal Elsewhere | Yes | 266 | 37.8 | 4.1 |
| Verbal Elsewhere | No | 466 | 62.2 | 4.1 |
| Verbal Elsewhere | Missing | 226 | - | |
| Boater Told | Yes | 63 | 10.5 | 3.0 |
| Boater Told | No | 637 | 89.5 | 3.0 |
| Boater Told | Missing | 258 | | |
| Survey | Yes | 77 | 11.7 | 2.0 |
| Survey | No | 631 | 88.3 | 2.0 |
| Survey | Missing | 250 | | |
| ı | | | | ı , |

| Maps | Yes | 303 | 39.9 | 5.5 |
|-------|---------|-----|------|-----|
| Maps | No | 509 | 60.1 | 5.5 |
| Maps | Missing | 146 | | |
| Other | Yes | 330 | 34.4 | 3.7 |
| Other | No | 628 | 65.6 | 3.7 |

Figure D-29. Source of Information about NDZ (Q25)




Table D-30. Organization that Boater Believes has Responsibility to Enforce NDZ (Q26)

| Organization | Response | Number | Weighted | |
|--------------|-------------|--------|----------|-------|
| 11000 | V | 500 | Percent | Error |
| USCG | Yes | 592 | 66.2 | 3.2 |
| USCG | No | 143 | 15.0 | 2.8 |
| USCG | Do Not Know | 172 | 18.8 | 1.6 |
| USCG | Missing | 51 | - | |
| State | Yes | 401 | 48.6 | 3.2 |
| State | No | 206 | 23.5 | 3.1 |
| State | Do Not Know | 242 | 27.8 | 1.7 |
| State | Missing | 109 | | |
| Local Govt | Yes | 258 | 33.6 | 3.4 |
| Local Govt | No | 281 | 33.3 | 3.5 |
| Local Govt | Do Not Know | 276 | 33.1 | 2.3 |
| Local Govt | Missing | 143 | | |
| Harbormaster | Yes | 435 | 51.5 | 3.7 |
| Harbormaster | No | 198 | 23.4 | 3.0 |
| Harbormaster | Do Not Know | 213 | 25.1 | 2.1 |
| Harbormaster | Missing | 112 | | |
| Marina | Yes | 268 | 34.2 | 4.1 |
| Marina | No | 296 | 34.8 | 3.9 |
| Marina | Do Not Know | 260 | 31.0 | 2.0 |
| Marina | Missing | 134 | | |
| EPA | Yes | 332 | 40.6 | 2.8 |
| EPA | No | 230 | 27.7 | 2.8 |
| EPA | Do Not Know | 265 | 31.7 | 2.1 |
| EPA | Missing | 131 | | |

Figure D-30. Organization that Boater Believes has Responsibility to Enforce NDZ (Q26)




Table D-31. Aware of Anyone Receiving Citation for Discharging Sewage in NDZ (Q27)

| Aware | Number | Weighted Percent | Standard Error |
|---------|--------|---------------------|-------------------|
| Yes | 49 | 5.4 | 0.8 |
| No | 901 | 94.6 | 0.8 |
| Missing | 8 | - | |

Figure D-31. Aware of Anyone Receiving Citation for Discharging Sewage in NDZ (Q27)





Table D-32. Notice of the Change in the Water Quality Since Area was Designated NDZ (Q28)

| Water Quality | Number | Weighted Percent | Standard Error |
|---------------|--------|---------------------|-------------------|
| Yes, Cleaner | 277 | 32.0 | 3.5 |
| Yes, Dirtier | 78 | 7.9 | 1.2 |
| No, Same | 440 | 45.2 | 3.6 |
| Do Not Know | 147 | 14.9 | 1.3 |
| Missing | 16 | | |

Figure D-32. Notice of the Change in the Water Quality Since Area was Designated NDZ (Q28)







Table D-33. Length of Boat (feet) by Whether Pumpout Facility Was Used (Q2 by Q16)

| Length of Boat (feet) | Whether Pumpout Facility Was Used | Number | Weighted Percent | Standard Error |
|-----------------------|--------------------------------------|--------|---------------------|-------------------|
| <20 | Yes | 3 | 16.6 | 9.1 |
| <20 | No | 17 | 83.4 | 9.1 |
| <20 | Appropriate skip | 37 | | - |
| 20-24.9 | Yes | 22 | 29.1 | 6.3 |
| 20-24.9 | No | 56 | 70.9 | 6.3 |
| 20-24.9 | Missing | 8 | | |
| 20-24.9 | Appropriate skip | 27 | | |
| 25-29.9 | Yes | 114 | 54.6 | 5.1 |
| 25-29.9 | No | 91 | 45.4 | 5.1 |
| 25-29.9 | Missing | 4 | - | |
| 25-29.9 | Appropriate skip | 10 | | |
| 30-34.9 | Yes | 155 | 70.2 | 3.7 |
| 30-34.9 | No | 61 | 29.8 | 3.7 |
| 30-34.9 | Missing | 1 | - | |
| 30-34.9 | Appropriate skip | 2 | - | |
| 35-39.9 | Yes | 100 | 72.2 | 4.5 |
| 35-39.9 | No | 39 | 27.8 | 4.5 |
| 35-39.9 | Missing | 1 | - | |
| 35-39.9 | Appropriate skip | 2 | - | |
| 40-44.9 | Yes | 70 | 68.0 | 5.1 |
| 40-44.9 | No | 32 | 32.0 | 5.1 |
| 40-44.9 | Appropriate skip | 5 | | - |
| 45+ | Yes | 59 | 61.2 | 4.6 |
| 45+ | No | 39 | 38.8 | 4.6 |
| 45+ | Appropriate skip | 1 | | |
| Missing | Yes | 1 | | - |
| Missing | No | 1 | | |

Figure D-33. Length of Boat (feet) by Whether Pumpout Facility Was Used (Q2 by Q16)




Length of Boat (feet)

Table D-34. Draft of Boat (feet) by Whether Pumpout Facility Was Used (Q3 by Q16)

| Draft of Boat (feet) | Whether Pumpout Facility Was Used | Number | Weighted Percent | Standard Error |
|-------------------------|--------------------------------------|--------|---------------------|-------------------|
| <2 | Yes | 17 | 27.4 | 7.5 |
| <2 | No | 39 | 72.6 | 7.5 |
| <2 | Missing | 4 | | |
| <2 | Appropriate skip | 29 | _ | |
| 2-2.9 | Yes | 91 | 56.4 | 6.1 |
| 2-2.9 | No | 65 | 43.6 | 6.1 |
| 2-2.9 | Missing | 4 | | |
| 2-2.9 | Appropriate skip | 22 | | |
| 3-3.9 | Yes | 219 | 68.1 | 3.3 |
| 3-3.9 | No | 103 | 31.9 | 3.3 |
| 3-3.9 | Missing | 4 | | |
| 3-3.9 | Appropriate skip | 11 | | |
| 4-4.9 | Yes | 97 | 60.4 | 4.6 |
| 4-4.9 | No | 61 | 39.6 | 4.6 |
| 4-4.9 | Missing | 1 | | |
| 4-4.9 | Appropriate skip | 4 | | |
| 5+ | Yes | 88 | 62.7 | 4.2 |
| 5+ | No | 55 | 37.3 | 4.2 |
| 5+ | Missing | 1 | | |
| 5+ | Appropriate skip | 7 | | |
| Missing | Yes | 12 | | |
| Missing | No | 13 | | |
| Missing | Appropriate skip | 11 | | |

Figure D-34. Draft of Boat (feet) by Whether Pumpout Facility Was Used (Q3 by Q16)




Draft of Boat (feet)

Table D-35. Function of Boat by Whether Pumpout Facility Was Used (Q4 by Q16)

| Function of Boat | Whether Pumpout Facility Was Used | Number | Weighted Percent | Standard Error |
|------------------|--------------------------------------|--------|---------------------|-------------------|
| Commercial | Yes | 18 | 52.3 | 6.6 |
| Commercial | No | 17 | 47.7 | 6.6 |
| Commercial | Appropriate skip | 16 | | |
| Recreational | Yes | 474 | 60.1 | 2.8 |
| Recreational | No | 309 | 39.9 | 2.8 |
| Recreational | Missing | 14 | | |
| Recreational | Appropriate skip | 69 | | |
| Live aboard | Yes | 86 | 68.4 | 3.9 |
| Live aboard | No | 37 | 31.6 | 3.9 |
| Live aboard | Appropriate skip | 1 | | |
| Missing | Yes | 1 | | |
| Missing | No | 2 | | - |

Figure D-35. Function of Boat by Whether Pumpout Facility Was Used (Q4 by Q16)



Function of Boat

Table D-36. Type of Boat by Whether Pumpout Facility Was Used (Q5 by Q16)

| Type of Boat | Whether Pumpout Facility Was Used | Number | Weighted Percent | Standard Error |
|--------------|--------------------------------------|--------|---------------------|-------------------|
| Power | Yes | 409 | 59.3 | 3.3 |
| Power | No | 269 | 40.7 | 3.3 |
| Power | Missing | 8 | | |
| Power | Appropriate skip | 78 | | |
| Sail | Yes | 116 | 63.5 | 4.0 |
| Sail | No | 71 | 36.5 | 4.0 |
| Sail | Missing | 6 | | |
| Sail | Appropriate skip | 5 | | |
| Missing | Yes | 3 | | |
| Missing | No | 2 | | |
| Missing | Appropriate skip | 1 | | |

Figure D-36. Type of Boat by Whether Pumpout Facility Was Used (Q5 by Q16)





Table D-37. Type of Toilet Operated by Whether Pumpout Facility Was Used (Q6 by Q16)

| Type of Toilet Operated | Whether Pumpout Facility Was Used | Number | Weighted Percent | Standard Error |
|----------------------------|--------------------------------------|--------|---------------------|-------------------|
| Portable | Yes | 28 | 20.4 | 4.3 |
| Portable | No | 100 | 79.6 | 4.3 |
| Portable | Missing | 8 | - | |
| Installed | Yes | 501 | 67.5 | 2.7 |
| Installed | No | 239 | 32.5 | 2.7 |
| Installed | Missing | 6 | - | |
| Missing | No | 3 | - | |
| Missing | Appropriate skip | 84 | | |

Figure D-37. Type of Toilet Operated by Whether Pumpout Facility Was Used (Q6 by Q16)




Type of Toilet Operated

Table D-38. Source of Training by Whether Pumpout Facility Was Used (Q9 by Q16)

| Source of Training | Whether Pumpout Facility Was Used | Number | Weighted Percent | Standard Error |
|--------------------|-----------------------------------|--------|---------------------|-------------------|
| Dealer | Yes | 123 | 67.4 | 4.5 |
| Dealer | No | 53 | 32.6 | 4.5 |
| Manufacturer | Yes | 21 | 70.0 | 7.0 |
| Manufacturer | No | 10 | 30.0 | 7.0 |
| Marina | Yes | 18 | 71.1 | 8.7 |
| Marina | No | 5 | 28.9 | 8.7 |
| Marina | Missing | 1 | | |
| Manual | Yes | 210 | 71.5 | 3.2 |
| Manual | No | 86 | 28.5 | 3.2 |
| Manual | Missing | 3 | | |
| Other | Yes | 162 | 61.7 | 3.4 |
| Other | No | 98 | 38.3 | 3.4 |
| Other | Missing | 1 | | |
| No training | Yes | 23 | 73.2 | 9.2 |
| No training | No | 10 | 26.8 | 9.2 |
| Missing | Yes | 5 | | |
| Missing | No | 2 | | |
| Missing | Missing | 1 | | |
| Appropriate skip | Yes | 23 | | |
| Appropriate skip | No | 94 | | - |
| Appropriate skip | Missing | 8 | | |
| Appropriate skip | Appropriate skip | 83 | | |

Figure D-38. Source of Training by Whether Pumpout Facility Was Used (Q9 by Q16)




Source of Training

Table D-39. Frequency of Boating in NDZ (days) by Whether Pumpout Facility Was Used (Q13 by Q16)

| Frequency of Boating in NDZ (days) | Whether Pumpout Facility Was Used | Number | Weighted Percent | Standard Error |
|------------------------------------|--------------------------------------|--------|---------------------|-------------------|
| 0 | Yes | 20 | 32.4 | 5.8 |
| 0 | No | 40 | 67.6 | 5.8 |
| 1-9 | Yes | 73 | 43.2 | 4.5 |
| 1-9 | No | 103 | 56.8 | 4.5 |
| 1-9 | Missing | 2 | | - |
| 10-19 | Yes | 84 | 58.7 | 5.7 |
| 10-19 | No | 56 | 41.3 | 5.7 |
| 10-19 | Missing | 3 | | - |
| 20-29 | Yes | 110 | 70.5 | 3.6 |
| 20-29 | No | 46 | 29.5 | 3.6 |
| 20-29 | Missing | 2 | | |
| 30-39 | Yes | 69 | 71.5 | 5.1 |
| 30-39 | No | 26 | 28.5 | 5.1 |
| 30-39 | Missing | 2 | | |
| 40-49 | Yes | 40 | 80.2 | 4.8 |
| 40-49 | No | 10 | 19.8 | 4.8 |
| 50-99 | Yes | 69 | 76.5 | 5.4 |
| 50-99 | No | 21 | 23.5 | 5.4 |
| 50-99 | Missing | 1 | | |
| 100+ | Yes | 50 | 66.1 | 4.0 |
| 100+ | No | 24 | 33.9 | 4.0 |
| 100+ | Missing | 1 | | |
| Missing | Yes | 9 | | |
| Missing | No | 10 | | |
| Missing | Missing | 3 | | .] |
| Appropriate skip | Appropriate skip | 84 | | |

Figure D-39. Frequency of Boating in NDZ (days) by Whether Pumpout Facility Was Used (Q13 by Q16)




Frequency of Boating in NDZ (days)

Table D-40. Whether Boater Discharged Sewage Outside NDZ by Whether Pumpout Facility Was Used (Q20 by Q16)

| Whether Boater Discharged Sewage Outside NDZ | Whether Pumpout Facility Was Used | Number | Weighted Percent | Standard Error |
|---|--------------------------------------|--------|---------------------|-------------------|
| Yes | Yes | 101 | 50.1 | 3.5 |
| Yes | No | 99 | 49.9 | 3.5 |
| Yes | Missing | 2 | | - |
| No | Yes | 418 | 63.8 | 3.0 |
| No | No | 231 | 36.2 | 3.0 |
| No | Missing | 2 | | - |
| Missing | Yes | 5 | | - |
| Missing | No | 6 | | · |
| Missing | Missing | 10 | | |
| Appropriate skip | Appropriate skip | 84 | | |

Figure D-40. Whether Boater Discharged Sewage Outside NDZ by Whether Pumpout Facility Was Used (Q20 by Q16)




Whether Boater Discharged Sewage Outside NDZ

Table D-41. NDZ Year of Origination by Whether Pumpout Facility Was Used (NDZ Age by Q16)

| | Whether Pumpout Facility Was Used | Number | Weighted Percent | Standard Error |
|-------------|--------------------------------------|--------|---------------------|-------------------|
| Before 1980 | Yes | 159 | 68.0 | 4.0 |
| Before 1980 | No | 71 | 32.0 | 4.0 |
| Before 1980 | Missing | 1 | | |
| Before 1980 | Appropriate skip | 12 | - | |
| Since 1980 | Yes | 365 | 57.7 | 3.3 |
| Since 1980 | No | 265 | 42.3 | 3.3 |
| Since 1980 | Missing | 13 | - | |
| Since 1980 | Appropriate skip | 72 | | |

Figure D-41. NDZ Year of Origination by Whether Pumpout Facility Was Used (NDZ Age by Q16)




NDZ Year of Origination

Table D-42. Length of Boat (feet) by Whether Boater had Problems (Q2 by Q17)

| Length of Boat (feet) | | Number | Weighted Percent | Standard Error |
|--------------------------|------------------|--------|---------------------|-------------------|
| <20 | Yes | 0 | 0.0 | 0.0 |
| <20 | No | 5 | 33.1 | 14.1 |
| <20 | No attempt | 15 | 66.9 | 14.1 |
| <20 | Appropriate skip | 37 | | |
| 20-24.9 | Yes | 5 | 5.4 | 2.1 |
| 20-24.9 | No | 58 | 75.1 | 4.9 |
| 20-24.9 | No attempt | 14 | 19.4 | 4.1 |
| 20-24.9 | Missing | 9 | | |
| 20-24.9 | Appropriate skip | 27 | | |
| 25-29.9 | Yes | 20 | 9.8 | 2.1 |
| 25-29.9 | No | 150 | 72.7 | 4.1 |
| 25-29.9 | No attempt | 34 | 17.5 | 3.5 |
| 25-29.9 | Missing | 5 | - | |
| 25-29.9 | Appropriate skip | 10 | - | |
| 30-34.9 | Yes | 20 | 9.4 | 2.3 |
| 30-34.9 | No | 157 | 75.0 | 3.4 |
| 30-34.9 | No attempt | 34 | 15.6 | 2.8 |
| 30-34.9 | Missing | 5 | - | |
| 30-34.9 | Appropriate skip | 3 | - | |
| 35-39.9 | Yes | 17 | 12.9 | 3.5 |
| 35-39.9 | No | 105 | 75.0 | 5.5 |
| 35-39.9 | No attempt | 17 | 12.1 | 2.8 |
| 35-39.9 | Missing | 1 | - | |
| 35-39.9 | Appropriate skip | 2 | | |
| 40-44.9 | Yes | 10 | 10.5 | 4.0 |
| 40-44.9 | No | 77 | 74.5 | 4.4 |
| 40-44.9 | No attempt | 15 | 15.0 | 3.8 |
| 40-44.9 | Appropriate skip | 5 | | |
| 45+ | Yes | 7 | 5.8 | 1.5 |
| 45+ | No | 78 | 81.8 | 3.5 |
| 45+ | No attempt | 12 | 12.3 | 3.4 |
| 45+ | Missing | 1 | | . |

| 45+ | Appropriate skip | 1 | .[| ı |
|---------|------------------|---|--------|---|
| Missing | No | 2 | | ı |

Figure D-42. Length of Boat (feet) by Whether Boater had Problems (Q2 by Q17)




Length of Boat (feet)

Table D-43. Draft of Boat (feet) by Whether Boater Had Problems (Q3 by Q17)

| Draft of Boat (feet) | Whether Boater Had Problems | Number | Weighted Percent | Standard Error |
|----------------------|--------------------------------|--------|---------------------|-------------------|
| <2 | Yes | 5 | 8.0 | 2.4 |
| <2 | No | 28 | 50.3 | 8.5 |
| <2 | No attempt | 22 | 41.6 | 7.9 |
| <2 | Missing | 5 | | |
| <2 | Appropriate skip | 29 | | |
| 2-2.9 | Yes | 14 | 8.3 | 3.2 |
| 2-2.9 | No | 117 | 75.7 | 3.8 |
| 2-2.9 | No attempt | 25 | 15.9 | 3.5 |
| 2-2.9 | Missing | 4 | - | |
| 2-2.9 | Appropriate skip | 22 | - | |
| 3-3.9 | Yes | 40 | 12.1 | 2.2 |
| 3-3.9 | No | 238 | 75.5 | 2.9 |
| 3-3.9 | No attempt | 41 | 12.4 | 1.7 |
| 3-3.9 | Missing | 7 | - | |
| 3-3.9 | Appropriate skip | 11 | - | |
| 4-4.9 | Yes | 9 | 6.5 | 2.6 |
| 4-4.9 | No | 122 | 76.7 | 3.5 |
| 4-4.9 | No attempt | 26 | 16.8 | 3.6 |
| 4-4.9 | Missing | 2 | - | |
| 4-4.9 | Appropriate skip | 4 | - | |
| 5+ | Yes | 10 | 7.8 | 2.5 |
| 5+ | No | 106 | 74.6 | 5.2 |
| 5+ | No attempt | 24 | 17.5 | 4.4 |
| 5+ | Missing | 3 | | |
| 5+ | Appropriate skip | 8 | | |
| Missing | Yes | 1 | | |
| Missing | No | 21 | | |
| Missing | No attempt | 3 | | |
| Missing | Appropriate skip | 11 | | |

Figure D-43. Draft of Boat (feet) by Whether Boater Had Problems (Q3 by Q17)




Draft of Boat (feet)

Table D-44. Function of Boat by Whether Boater Had Problems (Q4 by Q17)

| Function of Boat | Whether Boater Had Problems | Number | Weighted Percent | Standard Error |
|------------------|--------------------------------|--------|---------------------|-------------------|
| Commercial | Yes | 4 | 10.7 | 5.7 |
| Commercial | No | 25 | 70.6 | 8.6 |
| Commercial | No attempt | 6 | 18.7 | 6.5 |
| Commercial | Appropriate skip | 16 | | |
| Recreational | Yes | 71 | 9.1 | 1.3 |
| Recreational | No | 573 | 74.2 | 2.6 |
| Recreational | No attempt | 131 | 16.8 | 1.8 |
| Recreational | Missing | 21 | | |
| Recreational | Appropriate skip | 70 | | |
| Live aboard | Yes | 17 | 13.8 | 4.0 |
| Live aboard | No | 84 | 66.5 | 6.3 |
| Live aboard | No attempt | 21 | 19.7 | 4.1 |
| Live aboard | Missing | 1 | | |
| Live aboard | Appropriate skip | 1 | | |
| Missing | No | 3 | | |

Figure D-44. Function of Boat by Whether Boater Had Problems (Q4 by Q17)



Function of Boat

Table D-45. Type of Boat by Whether Boater Had Problems (Q5 by Q17)

| Type of Boat | Whether Boater Had Problems | Number | Weighted Percent | Standard Error |
|--------------|--------------------------------|--------|---------------------|-------------------|
| Power | Yes | 68 | 9.7 | 1.6 |
| Power | No | 498 | 74.3 | 2.5 |
| Power | No attempt | 106 | 16.0 | 1.7 |
| Power | Missing | 14 | | |
| Power | Appropriate skip | 78 | | |
| Sail | Yes | 11 | 6.9 | 2.3 |
| Sail | No | 136 | 73.0 | 5.0 |
| Sail | No attempt | 38 | 20.2 | 4.6 |
| Sail | Missing | 7 | | |
| Sail | Appropriate skip | 6 | | |
| Missing | No | 5 | | |
| Missing | Appropriate skip | 1 | | |

Figure D-45. Type of Boat by Whether Boater Had Problems (Q5 by Q17)





Table D-46. Type of Toilet Operated by Whether Boater Had Problems (Q6 by Q17)

| Type of Toilet Operated | Whether Boater Had Problems | Number | Weighted Percent | Standard Error |
|----------------------------|--------------------------------|--------|---------------------|-------------------|
| Portable | Yes | 1 | 0.7 | 0.6 |
| Portable | No | 87 | 67.1 | 7.2 |
| Portable | No attempt | 40 | 32.2 | 7.1 |
| Portable | Missing | 8 | | |
| Installed | Yes | 78 | 10.6 | 1.7 |
| Installed | No | 552 | 75.6 | 2.7 |
| Installed | No attempt | 102 | 13.8 | 1.8 |
| Installed | Missing | 13 | | |
| Installed | Appropriate skip | 1 | | |
| Missing | No | 2 | | |
| Missing | No attempt | 1 | | |
| Missing | Appropriate skip | 84 | | |

Figure D-46. Type of Toilet Operated by Whether Boater Had Problems (Q6 by Q17)




Type of Toilet Operated

Table D-47. Source of Training by Whether Boater Had Problems (Q9 by Q17)

| Source of Training | Whether Boater Had Problems | Number | Weighted Percent | Standard Error |
|--------------------|--------------------------------|--------|---------------------|-------------------|
| Dealer | Yes | 20 | 10.8 | 2.0 |
| Dealer | No | 142 | 81.4 | 2.5 |
| Dealer | No attempt | 13 | 7.8 | 2.5 |
| Dealer | Missing | 1 | | |
| Manufacturer | Yes | 4 | 12.7 | 6.7 |
| Manufacturer | No | 19 | 64.6 | 8.1 |
| Manufacturer | No attempt | 8 | 22.8 | 5.9 |
| Marina | Yes | 1 | 3.8 | 3.6 |
| Marina | No | 16 | 64.8 | 10.5 |
| Marina | No attempt | 6 | 31.3 | 8.8 |
| Marina | Missing | 1 | | |
| Manual | Yes | 30 | 10.1 | 2.3 |
| Manual | No | 225 | 77.8 | 3.4 |
| Manual | No attempt | 36 | 12.1 | 2.3 |
| Manual | Missing | 7 | | |
| Manual | Appropriate skip | 1 | | |
| Other | Yes | 26 | 10.8 | 2.4 |
| Other | No | 186 | 71.7 | 4.6 |
| Other | No attempt | 44 | 17.5 | 2.9 |
| Other | Missing | 5 | | |
| No training | Yes | 2 | 5.8 | 3.6 |
| No training | No | 28 | 85.8 | 5.6 |
| No training | No attempt | 3 | 8.3 | 4.3 |
| Missing | No | 5 | | |
| Missing | No attempt | 2 | | |
| Missing | Missing | 1 | | |
| Appropriate skip | Yes | 1 | | |
| Appropriate skip | No | 78 | | |
| Appropriate skip | No attempt | 38 | | |
| Appropriate skip | Missing | 8 | | |
| Appropriate skip | Appropriate skip | 83 | | |

Figure D-47. Source of Training by Whether Boater Had Problems (Q9 by Q17)




Source of Training

Table D-48. Frequency of Boating in NDZ (days) by Whether Boater Had Problems (Q13 by Q17)

| Frequency of | Whether Boater | Number | Weighted | Standard |
|-----------------------|------------------|--------|----------|----------|
| Boating in NDZ (days) | Had Problems | | Percent | Error |
| 0 | Yes | 3 | 3.6 | 2.4 |
| 0 | No | 45 | 74.4 | 4.1 |
| 0 | No attempt | 12 | 22.0 | 4.0 |
| 1-9 | Yes | 10 | 5.5 | 2.1 |
| 1-9 | No | 106 | 63.8 | 4.6 |
| 1-9 | No attempt | 56 | 30.6 | 4.6 |
| 1-9 | Missing | 6 | _ : | - |
| 10-19 | Yes | 11 | 7.5 | 2.6 |
| 10-19 | No | 108 | 79.1 | 3.4 |
| 10-19 | No attempt | 18 | 13.4 | 2.2 |
| 10-19 | Missing | 6 | | |
| 20-29 | Yes | 12 | 8.2 | 2.3 |
| 20-29 | No | 127 | 81.7 | 3.1 |
| 20-29 | No attempt | 16 | 10.1 | 2.1 |
| 20-29 | Missing | 2 | | - |
| 20-29 | Appropriate skip | 1 | | - |
| 30-39 | Yes | 7 | 7.2 | 2.6 |
| 30-39 | No | 80 | 83.4 | 4.4 |
| 30-39 | No attempt | 8 | 9.5 | 3.4 |
| 30-39 | Missing | 2 | | |
| 40-49 | Yes | 4 | 8.1 | 3.1 |
| 40-49 | No | 40 | 80.9 | 4.2 |
| 40-49 | No attempt | 6 | 11.0 | 3.6 |
| 50-99 | Yes | 15 | 16.3 | 2.9 |
| 50-99 | No | 64 | 70.1 | 5.0 |
| 50-99 | No attempt | 12 | 13.6 | 3.4 |
| 100+ | Yes | 16 | 22.2 | 6.7 |
| 100+ | No | 48 | 63.2 | 6.9 |
| 100+ | No attempt | 10 | 14.6 | 3.5 |
| 100+ | Missing | 1 | | |
| Missing | Yes | 1 | | |
| Missing | No | 14 | | |
| ľ | | | | |

| Missing | No attempt | 3 |] |
|------------------|------------------|----|---|
| Missing | Missing | 4 | |
| Appropriate skip | Appropriate skip | 84 | |

Figure D-48. Frequency of Boating in NDZ (days) by Whether Boater Had Problems (Q13 by Q17)




Frequency of Boating in NDZ (days)

Table D-49. Adverse Conditions Experienced by Boater by Whether Boater Had Problems (Q21 by Q17)

| Adverse Conditions Experienced by Boater | Whether Boater Had Problems | Number | Weighted Percent | Standard Error |
|---|--------------------------------|--------|---------------------|-------------------|
| Marina Closed | Yes | 11 | 31.6 | 8.3 |
| Marina Closed | No | 26 | 65.7 | 8.4 |
| Marina Closed | No attempt | 1 | 2.7 | 2.5 |
| No Pumpout | Yes | 12 | 26.6 | 10.2 |
| No Pumpout | No | 37 | 69.9 | 10.4 |
| No Pumpout | No attempt | 2 | 3.5 | 2.3 |
| No Pumpout | Appropriate skip | 1 | | |
| Not Functioning | Yes | 56 | 56.6 | 6.1 |
| Not Functioning | No | 40 | 38.2 | 7.0 |
| Not Functioning | No attempt | 5 | 5.2 | 2.7 |
| No Staff | Yes | 25 | 65.2 | 8.5 |
| No Staff | No | 14 | 34.8 | 8.5 |
| No Staff | No attempt | 0 | 0.0 | 0.0 |
| No Staff | Missing | 1 | | |
| Don`t Know How | Yes | 6 | 61.1 | 13.0 |
| Don`t Know How | No | 3 | 31.8 | 13.6 |
| Don`t Know How | No attempt | 1 | 7.2 | 6.3 |
| Inaccessible | Yes | 13 | 43.4 | 9.1 |
| Inaccessible | No | 15 | 47.8 | 8.0 |
| Inaccessible | No attempt | 3 | 8.9 | 4.2 |
| Boat Unavailable | Yes | 12 | 40.7 | 8.2 |
| Boat Unavailable | No | 16 | 56.1 | 8.6 |
| Boat Unavailable | No attempt | 1 | 3.1 | 2.7 |
| Long Waiting Times | Yes | 11 | 34.7 | 8.0 |
| Long Waiting Times | No | 22 | 65.3 | 8.0 |
| Long Waiting Times | No attempt | 0 | 0.0 | 0.0 |
| High Cost | Yes | 7 | 26.6 | 10.2 |
| High Cost | No | 22 | 70.2 | 10.4 |
| High Cost | No attempt | 1 | 3.2 | 2.9 |
| High Cost | Appropriate skip | 1 | | |
| Long Way to Pumpout | Yes | 3 | 27.3 | 16.6 |
| Long Way to Pumpout | No | 8 | 59.5 | 14.7 |

| Long Way to Pumpout | No attempt | 2 | 13.2 | 7.5 |
|-------------------------------|------------------|----|------|-----|
| No adverse conditions checked | Yes | 1 | 52.3 | |
| No adverse conditions checked | No | 1 | 47.7 | |
| Missing | Yes | 5 | | |
| Missing | No | 91 | | |
| Missing | No attempt | 41 | | |
| Missing | Missing | 16 | - | |
| Appropriate skip | Appropriate skip | 84 | | |


Figure D-49. Adverse Conditions Experienced by Boater by Whether Boater Had Problems (Q21 by Q17)



Adverse Conditions Experienced by Boater


multiple response item - observations may be classifed in more than one bar

Figure D-50. Adverse Conditions Experienced by Boater by Whether Boater Had Problems (Q21 by Q17)



Adverse Conditions Experienced by Boater

Figure D-51. Adverse Conditions Experienced by Boater by Whether Boater Had Problems (Q21 by Q17)




Adverse Conditions Experienced by Boater

Table D-52. NDZ Year of Origination by Whether Boater had Problems (NDZ Age by Q17)

| | Whether Boater had Problems | Number | Weighted Percent | Standard Error |
|-------------|-----------------------------|--------|---------------------|-------------------|
| Before 1980 | Yes | 27 | 12.2 | 2.8 |
| Before 1980 | No | 147 | 64.0 | 4.3 |
| Before 1980 | No attempt | 54 | 23.8 | 3.1 |
| Before 1980 | Missing | 2 | | |
| Before 1980 | Appropriate skip | 13 | | |
| Since 1980 | Yes | 52 | 8.1 | 1.6 |
| Since 1980 | No | 485 | 77.6 | 2.8 |
| Since 1980 | No attempt | 87 | 14.3 | 1.9 |
| Since 1980 | Missing | 19 | | |
| Since 1980 | Appropriate skip | 72 | | |

Figure D-52. NDZ Year of Origination by Whether Boater had Problems (NDZ Age by Q17)




NDZ Year of Origination

Table D-53. Whether Boater Discharged Sewage Outside NDZ by Whether Boater was Deterred from Using Pumpout Equipment (Q20 by Q22)

| Whether Boater Discharged Sewage Outside NDZ | Whether Boater was Deterred from Using Pumpout Equipment | Number | Weighted Percent | Standard Error |
|--|--|--------|---------------------|-------------------|
| Yes | Yes | 30 | 19.3 | 7.9 |
| Yes | No | 124 | 80.7 | 3.0 |
| Yes | Missing | 35 | | |
| Yes | Appropriate skip | 13 | | |
| No | Yes | 46 | 7.6 | 7.9 |
| No | No | 538 | 92.4 | 3.0 |
| No | Missing | 49 | | |
| No | Appropriate skip | 18 | | |
| Missing | Yes | 2 | | |
| Missing | No | 5 | | |
| Missing | Missing | 13 | | |
| Missing | Appropriate skip | 1 | | |
| Appropriate skip | Appropriate skip | 84 | | |

Figure D-53. Whether Boater Discharged Sewage Outside NDZ by Whether Boater was Deterred from Using Pumpout Equipment (Q20 by Q22)




Whether Boater Discharged Sewage Outside NDZ

Table D-54. Whether Boater Discharged Sewage Outside NDZ by Whether Boater Found Working Pumpout Equipment (Q20 by Q19)

| Whether Boater Discharged Sewage Outside NDZ | Whether Boater Found Working Pumpout Equipment | Number | Weighted Percent | Standard Error |
|--|--|--------|---------------------|-------------------|
| Yes | Yes | 25 | 14.2 | 7.7 |
| Yes | No | 174 | 85.8 | 2.7 |
| Yes | Missing | 3 | | |
| No | Yes | 32 | 4.9 | 7.7 |
| No | No | 615 | 95.1 | 2.7 |
| No | Missing | 4 | | |
| Missing | No | 5 | | |
| Missing | Missing | 16 | | |
| Appropriate skip | Appropriate skip | 84 | | |

Figure D-54. Whether Boater Discharged Sewage Outside NDZ by Whether Boater Found Working Pumpout Equipment (Q20 by Q19)



Whether Boater Discharged Sewage Outside NDZ